

1.
5232

✓ ELSON ROAD

Boundary wall of
St Thomas' Churchyard

SU 60 SW 2/40

II

GV

original list

2.

Mid C19. Stone wall in squared rubble, with capping, completely surrounding the rectangular churchyard. One narrow entrance is formed by the wall being turned, to form flanking to 5 steps. Main entrance has stone piers, with steep weathering, chamfered corners and plinth; joined by wrought iron overthrow, tapered with scrolling between the outer frames, supporting a lamp bracket. Metal gates.
